



Customer: Leinster Sample Report	Report Date:
Address: Greenhills Road Tallaght Dublin 24	PO No: 123456
Contact Name: Alison McDermott	Engineer: Paul Grant
Site Name: Leinster Sample Report	Job Type: Fit out
Site Address: Greenhills Road Tallaght	Charge Type: Price agreed
Reported By: Joanne Duffy	Location:

Report Fault / Work Requested:

Urgent

Date / Time Logged

01-01-1900 00:00

Apt 123 Block 123
4 x new dining chairs and removal of old
Remove television stand
Paint walls throughout
Replace rubber seal on shower screen in main bathroom and on shower tray in ensuite
Double mattress protector x 2 for beds
Deep clean of whole apartment inc appliances
Tidy away cabling at front door
Electrical and plumbing check

Work Carried Out:

Work Completed

All works have been carried out as per specification
When changing light bulbs it was noted that a low voltage transformer was faulty - we replaced this also.

Additional Comments / Work Required:

Follow On Call Required

Engineers Hours	Labour Type	Hours
James McDonald	ADDITIONAL_HRS	1
Tomasz Ciupa	STANDARD_HRS	1

Parking Costs: €0

Toll Costs: €0

Other Costs: €0

Parts Used	Description	Quantity
MISC_PART	Lighting transformer	1
MISC_PART	replacement bulbs	5



Photos Captured



Bulbs Replaced



kitchen bulbs replaced



dining chairs



bedroom 1



bedroom 2



bath seal



shower seal



cables tidied

Customer Signature:

N/A

Tradesman Signature:

BOC